

Computer Numerical Control



Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT

- Computerized numerical control (CNC) machines
 - Perform complex operations faster, more accurately and consistently



Examples of some workpieces produced by CNC machines.



Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT

A CNC lathe.



Tools are changed manually

Photo courtesy of Haas Automation, Inc



Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT



Courtesy of Hardinge, Inc.

CNC turning center.



Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT

A CNC milling machine.

Tools are
changed
manually



Photo courtesy of Haas Automation, Inc.



Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT



Photo courtesy of Haas Automation, Inc.

CNC machining center.

Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT



The CNC Machine Control Unit

- CNC program created & stored in MCU (machine control unit)

An operator control panel mounted on the exterior of the machine control unit.




Copyright © 2015 Cengage Learning™



CNC Motion Control

- Machine locates axes from programmed commands
- Components: drive screws, CNC guideways, servo motors






Copyright © 2015 Cengage Learning®

A ballscrew assembly.



Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT



Copyright © 2015 Cengage Learning™

A linear guide assembly and its parts.




Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT

Coordinate Systems

- Programs tell machine function and where to perform it
- Coordinate system maps locations
 - Cartesian/rectangular system maps positive/negative values on X- and Y- axes relative to origin
 - Polar system locates points by angle and distance from origin






Copyright © 2015 Cengage Learning®

The parts of a servo motor.






Copyright © 2015 Cengage Learning®

The parts of the Cartesian coordinate system.



Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT



Copyright © 2015 Cengage Learning®


Quadrants separate a coordinate plane into four regions.




Richland College

DALLAS COUNTY COMMUNITY COLLEGE DISTRICT

A diagram showing the polar coordinate system. When using this system, the X-value specifies the distance from the origin, and the Y-value specifies the angle relative to the zero degree mark. The position "A" shown is located at an angle of 45° and a distance of 8.0" from the origin; when using the polar coordinate system this is written as X8.0 Y45.0



An example of how each position in an eight-hole workpiece can be identified using polar coordinates. The positions for each location are programmed as: (A) X7.0 Y0; (B) X7.0 Y45.0; (C) X7.0 Y 90.0; (D) X7.0 Y135.0; (E) X7.0 Y180.0; (F) X7.0 Y225.0; (G) X7.0 Y270.0; (H) X7.0 Y315.0




Positioning Systems


- Absolute positioning system references all positions relative to origin
- Incremental positioning system specifies distance from current position to next



Assume that each block on the grid equals 1". Using the absolute programming method, the coordinates for each identified location are: (A) X6.0 Y6.0; (B) X-6.0 Y6; (C) X-6.0 Y-6; (D) X6.0 Y-6.0.



Assume that each block on the grid equals 1". Using the incremental programming method, assuming the cutting tool is already at position A, the coordinates for each following location are: (B) X-12.0 Y0; (C) X0.0 Y-12; (D) X12.0 Y0.0



Codes

- Codes tell machine what to do at position
 - G-codes: preparatory commands (set mode)
 - M-codes: miscellaneous functions (on/off)
 - Other word address commands
 - Binary



Parameter Number	Bit Number							
	#7	#6	#5	#4	#3	#2	#1	#0
0401	1	1	0	1	0	0	0	1

An example of the parameter numbering format. Notice the parameter number is 0401 and the bits are read in sequence from right to left. Each bit can be either a '0' or a '1'.



Conversational-Type Programming


- Operator selects function and machine prompts for more information



Parts of a CNC Program

- Safe-start: clears machine for new operation
- Material removal: performs operations
- Program ending: safely positions tool & axes out of the way





O0001 (SAMPLE PROGRAM);

G0G90G20;

M6T1;

X1.Y1.(POSITION "A");

Z0.1S4500M3;

Program number and (operator label). Since this label is within parentheses, it is not read by the machine, only by the operator.


Safe start block initiating the modal codes for rapid traverse (G0), absolute programming (G90), and inch units (G20)

Tool change to tool #1

Rapid to X1. Y1. (Position "A"). Rapid and absolute modes are still modal from above so they do not need to be programmed again here.

Move the Z-axis to 0.1, start spindle in forward direction to 4500 RPM. The Z-axis move is a rapid move because the G0 is still active.

The program begins by the tool being loaded, the spindle being started, and the tool being rapid positioned to the first location.



G1Z-0.1F14.0; ←

Y2.0 (POSITION "B"); ←

X2.0 (POSITION "C"); ←

G2X4.0 Y2.0 R1.0 (POSITION "D"); ←

G0Z0.1; ←

Linear axis motion feeds the tool tip to Z-0.1 at a feed rate of 14 inches per minute.

Feed move to Y2.0 (Position "B"). G1-linear is still modal.

Feed move to X2.0 (Position "C"). G1-linear is still modal.


Feed move in a CW arc to X4.0, Y2.0 (Position "D"), at a radius of 1.0

Rapid the Z-axis up to Z0.1

Copyright © 2015 Cengage Learning

The tool is fed to depth and then fed to each location. Once machining is complete, the tool is then retracted to a clearance point above the workpiece.

The tool is rapid positioned to a location far above the workpiece. The coolant is turned off and the program is ended.



- `G0Z6.0;` ← Rapid the Z-axis up to Z6.0. This moves the tool away from part.
- `M9;` ← Turn coolant off
- `M30;` ← End program and reset

