### Surface Finish Measurement

#### Objectives

- Interpret the surface finish symbols that appear on a drawing
- Use a surface finish indicator to measure the surface finish of a part

#### Surface Finish Measurement


- Modern technology demanding improved surface finishes
  - Often require additional operations: lapping or honing
- System of symbols devised by ASA
  - Provide standard system of determining and indicating surface finish
  - Inch unit is microinch (μin)
  - Metric unit is micrometer (μm)

#### Surface Indicator

- Tracer head and amplifier
- Tracer head has diamond stylus, point radius .0005 µin that bears against work surface
- Movement caused by surface irregularities converted into electrical fluctuations
- Signals magnified by amplifier and registered on meter
- Reading indicates average height of surface




Either arithmetic average roughness height (Ra) or root mean square (Rq)



$$R_a = \frac{237}{13} = 18.2 \,\mu\text{in}.$$
 $R_n = \sqrt{\frac{5179}{13}} = 19.9 \,\mu\text{in}.$ 

## Symbols Used to Identify Surface Finishes and Characteristics



#### Surface Finish Definitions

- Surface deviations: departures from nominal surface in form of waviness, roughness, flaws, lay, and profile
- Waviness: surface irregularities that deviate from mean surface in form of waves
- Waviness height: peak-to-valley distance in inches or millimeters
- Waviness width: distance between successive waviness peaks or valleys in inches or millimeters

#### Surface Finish Definitions

- Roughness: relatively finely spaced irregularities superimposed on waviness pattern
  - Caused by cutting tool or abrasive grain action
  - Irregularities narrower than waviness pattern
- Roughness height: Ra deviation measured normal to centerline in microinches or μm
- Roughness width: distance between successive roughness peaks parallel to nominal surface in inches or millimeters
- Profile: contour of specified section through a surface

#### Surface Finish Definitions

- Roughness width cutoff: greatest spacing of repetitive surface irregularities included in measurement of roughness height
  - Must be greater than roughness width
- Flaws: irregularities such as scratches, holes, cracks, ridges, or hollows that do not follow regular pattern
- Lay: direction of predominant surface pattern caused by machining process

#### Symbols that Indicate Direction of Lay

- Parallel to boundary line of surface indicated by symbol
- \_|\_ Perpendicular to boundary line of surface indicated by symbol
- X Angular in both directions on surface indicated by symbol
- M Multidirectional
- C Approximately circular to center of the surface indicated by symbol
- R Approximately radial in relation to the center of surface indicated by symbol

### Average surface roughness produced by standard machining processes

Microinches		Micrometers
Turning	100–250	2.5–6.3
Drilling	100–200	2.5–5.1
Reaming	50–150	1.3–3.8
Grinding	20–100	0.5–2.5
Honing	5–20	0.13-0.5
Lapping	1–10	0.025-0.254

# To Measure Surface Finish with a Surface Indicator

- 1. Turn on, allow instrument to warm up
- 2. Check machine calibration by moving stylus over test block
- 3. Adjust calibration control if necessary
- 4. Use .030-in cutoff range for surface roughness of 30  $\mu$ in or more. For less, use the .010 in. cutoff range
  - Unless specified otherwise

# To Measure Surface Finish with a Surface Indicator

- Thoroughly clean surface to be measured
  - Ensures accurate readings
  - Reduces wear on rider cap protecting stylus
- Using smooth, steady movement of stylus, trace work surface at approximately
   .125 in./s
- 7. Note reading from meter scale

#### Other Methods

- Surface analyzer
  - Uses recording device to reproduce surface irregularities on graduated chart, providing ink-line record
- Comparison blocks
  - Used for comparing finish on workpiece with calibrated finish on test block using fingernail test
- Commercial sets of standard finished specimens
  - Up to 25 different surface finish samples