CNC Turning Basics



- CNC turning like manual lathe or milling machine
- Z-axis = motion along slide, X-axis = perpendicular



The coordinate system for CNC turning and the relationship of the axes.





The origin for turning is usually located on the workpiece face on the part center line.

Richland College

R



A slant-bed turning center has an inclined bed.





An end-working live tooling attachment for milling and performing holemaking operations on the face of a part.

Richland College

R



An adjustable angle-head live tooling attachment allows angular milling to be performed on the turning center.





A robotic manufacturing cell can enhance productivity by minimizing operator intervention. The workpiece is transferred between machines by the robot.



A specialized mill/turn machine that can perform heavy milling and turning operations.







A sub-spindle opposes the machine's main spindle. The workpiece can be transferred from the main spindle to the sub-spindle so that the backside of the workpiece can be machined.



R

Types of Turning Machines

 Turret-type machines, gang-tool-type machines, CNC lathes, Swiss-type turning centers



A circular turret holds multiple tools and can index to any one of them with a program command.



Richland College

R



A twin turret machine can move both turrets independently for machining.

Richland College

R

A gang tool machine top plate with the tools arranged in a row.





R



Courtesy of Hardinge, Inc

A gang tool turning center.



R

A CNC lathe holds cutting tools with a tool post similar to that used on a manual lathe.





R

Photo courtesy of Haas Automation, I



A Swiss turning machine moves the entire workpiece in the Z-axis instead of moving the cutting tool.



A typical tool arrangement on a Swiss turning machine.





Tool-Mounting Adapters

- Styles of tool-mounting adapters for different machines
 - Each accepts tools differently
 - CNC machines use same types of cutting tools as non-CNC, but different holding methods





This type of toolholding adapter bolts directly to the turret with cap screws.





A VDI toolholding adapter mounts to the turret with a VDI shank. The adapter is drawn tight to the turret with the serrated teeth.

Richland College

R



A dovetail mounting system used on a gang tool machine.



R



Quick-change toolholders used on a CNC lathe.





A CNC collet chuck for holding holemaking tools.

Richland College

R



The collet types shown from left to right are the ER series, DA series, and TG series.





A Hardinge HDB drill bushing used to hold holemaking tools.





The turning tool orientations shown are right hand, neutral, and left hand.





Cutoff inserts are available with a biased cutting edge to minimize burrs on the part being cut off.

Richland College

R



A grooving tool is in the foreground and a cutoff tool is in the background.





A gripping-ring-type bar puller grips the bar end by sliding a ring of spring-steel teeth over the perimeter of the bar.

Richland College

R



This coolant-actuated bar puller's jaws grip the stock using the hydraulic pressure of the machine's coolant system.

Richland College

R



Photo courtesy of Haas Automation, Inc

A CNC turning center equipped with an automatic bar feeder.



R

Workholding

- Workholding devices for CNC like those for manual lathes
 - Types: workholding collets, workholding chucks



Copyright © 2015 Congage Le

collet for workholding.





A three-jaw power-actuated chuck in a CNC turning center. This setup is using soft jaws that were machined to match the outside diameter of the workpiece.

Richland College

R

Process Planning

- Manufacturing process: all operations required to machine a part
- Process plan describes all steps in detail
 - Includes a description of each operation, the tools required, speed and feed data, workholding information, other notes and comments, and often a sketch depicting the part orientation

